

TO FIT SIZE CHART

*Measurements refer to body size, not garment dimensions



R124X - RIPSTOP SOFT SHELL WORKWEAR JACKET

25.02.2016

	S	M	L	XL	2XL	3XL	4XL
Full chest in inches*	38	41	44	46	48	50	52
Full chest in cm*	96,52	104,14	111,76	116,84	121,92	127	132,08
German clothing size (men)	48	50	54	56	58	60	62

HOW TO MEASURE CHEST: Place the tape measure across the back, underneath the arms and then across the fullest part of the chest.

1 Inch = 2,54 cm